

## DESCRIPTION OF DRAWINGS

- #1 Existing full length showing opening.
- #2 Existing "cape", shorter gown showing opening in the middle and flaps on both sides
- #3 Double paper clip closure device
- #4 Alligator clamps
- #5 Opening alligator clamps
- #6 Double sided tape" with strong adhesive on outer surfaces and light resealable adhesive on inner surfaces. Protective strip shown peeled back from outer surfaces.
- #7 Strong adhesive on outer surfaces.
- #8 Light adhesive on inner surfaces
- #9 Inner surfaces, attached, opened, reattached
- #10a Protective strip pulled back, outer surfaces attached to gown, inner resealable surfaces not attached.
- #10b Cross section showing both protective strips peeled back and outer surfaces being attached to both sides of the gown.
- #10c Outer surfaces attached to gown
- #11 Inner surfaces separated by pulling gown open
- #12 Inner surfaces being resealed
- #13a Tie closure device showing strings attached to base which sticks to gown.
- #13b Tie closure device with base stuck to gown.
- #13 Strings tied and gown closed
- #14a Corners of paper gown cut into the shape of strings extending from the corners
- #14b Paper strings tied
- #15 Alligator clip holding two flaps together